

DOOR SCHEDULE																	DOOR & HARDWARE NOTE																
NO	ROOM	DOOR						DOOR FRAME DET.						HDW	LBL	COMMENTS	NO	ROOM	DOOR						DOOR FRAME DET.						HDW	LBL	COMMENTS
		WIDTH	HEIGHT	THK	TYP	MAT	FIN	H	J	J	T	MAT	FIN						WIDTH	HEIGHT	THK	TYP	MAT	FIN	H	J	J	T	MAT	FIN			
46	CUSTOMER CALL CENTER 154	3'-0"	8'-0"	1 3/4"	A	6	6	A15	A15	A15	-	6	6	6	-	NEW SOLID CORE WOOD DOOR IN THICKER WALL	1	MEDIUM CONF. ROOM 102	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
47	COMPUTER 158	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR	2	DIRECTOR ACCOUNTING 103	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
48	BREAK 159	3'-0"	8'-0"	1 3/4"	A	3	3	A15	A15	A15	-	3	3	3	-	NEW SOLID CORE WOOD DOOR/CLOSER	3	CFO 104	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
49	BREAK 159	3'-0"	8'-0"	1 3/4"	A	3	3	A15	A15	A15	-	3	3	3	-	NEW SOLID CORE WOOD DOOR/CLOSER	4	ACCOUNTING 105	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
50	HALLWAY 160	3'-0"	8'-0"	1 3/4"	A	3	3	A15	A15	A15	-	3	3	3	-	NEW SOLID CORE WOOD DOOR/CLOSER	5	ACCOUNTING 106	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
51	WOMEN 161	3'-0"	8'-0"	1 3/4"	C	5	5	A15	A15	A15	-	5	5	5	-	NEW SOLID CORE WOOD DOOR/CLOSER/PUSH-PULL	6	CORRIDOR 107	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
52	MEN 162	3'-0"	8'-0"	1 3/4"	C	5	5	A15	A15	A15	-	5	5	5	-	NEW SOLID CORE WOOD DOOR/CLOSER/PUSH-PULL	7	ACCOUNTING STO 109	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
53	HALLWAY 160	3'-0"	8'-0"	1 3/4"	A	3	3	A15	A15	A15	-	3	3	3	-	NEW SOLID CORE WOOD DOOR/CLOSER	8	PHARMACY STO. 110	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E1	LOBBY 100	(2)3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING STOREFRONT DOOR	9	BREAK 111	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E2	LOBBY 100	(2)3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING WOOD DOUBLE DOORS TO BE RE-FINISHED	10	STO. 112	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E3	LOBBY 100	(2)3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING WOOD DOUBLE DOORS TO BE RE-FINISHED	11	UNISEX 114	3'-0"	8'-0"	1 3/4"	A	2	2	A15	A15	A15	-	2	2	2	-	NEW SOLID CORE WOOD DOOR/CLOSER/PRIVACY LOCKS
E4	LOBBY 100	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING WOOD DOOR TO BE RE-FINISHED	12	UNISEX 115	3'-0"	8'-0"	1 3/4"	A	2	2	A15	A15	A15	-	2	2	2	-	NEW SOLID CORE WOOD DOOR/CLOSER/PRIVACY LOCKS
E5	VEST. 118B	3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING STOREFRONT DOOR TO REMAIN	13	WOMEN 116	3'-0"	8'-0"	1 3/4"	A	2	2	A15	A15	A15	-	2	2	2	-	NEW SOLID CORE WOOD DOOR/CLOSER/PRIVACY LOCKS
E6	PHARMACY CALL CENTER 119	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXT'G RATED DOOR TO BE REPAINTED WITH NEW PAINTED RATED FRAME	14	MEN 117	3'-0"	8'-0"	1 3/4"	A	2	2	A15	A15	A15	-	2	2	2	-	NEW SOLID CORE WOOD DOOR/CLOSER/PRIVACY LOCKS
E7	UNISEX 121	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED DOOR & FRAME TO REMAIN AND BE REPAINTED	15	VEST. 118B	3'-0"	8'-0"	1 3/4"	A	3	3	A15	A15	A15	-	3	3	3	-	NEW SOLID CORE WOOD DOOR/CLOSER
E8	JANITOR 122	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED DOOR & FRAME TO REMAIN AND BE REPAINTED	16	CORRIDOR 118A	3'-0"	8'-0"	1 3/4"	A	3	3	A15	A15	A15	-	3	3	3	-	NEW SOLID CORE WOOD DOOR/CLOSER
E9	MARKETING 135	3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING STOREFRONT DOOR TO REMAIN REMOVE EXISTING HARDWARE	17	PHARMACY CALL CENTER 119	3'-0"	8'-0"	1 3/4"	A	3	3	A15	A15	A15	-	3	3	3	-	NEW SOLID CORE WOOD DOOR/CLOSER
E10	COPY 137	3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING STOREFRONT DOOR TO REMAIN REMOVE EXISTING HARDWARE	18	PHARMACY OFFICE 120	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E11	CEO 146	3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING STOREFRONT DOOR TO REMAIN REMOVE EXISTING HARDWARE	19	LARGE CONF. ROOM 124	3'-0"	9'-0"	1 3/4"	B	4	4	-	-	-	4	4	4	-	NEW HERCULITE DOOR	
E12	DIRECTOR HR 148	3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING STOREFRONT DOOR TO REMAIN REMOVE EXISTING HARDWARE	20	LARGE CONF. ROOM 124	3'-0"	9'-0"	1 3/4"	B	4	4	-	-	-	4	4	4	-	NEW HERCULITE DOOR	
E13	COMMON CORRIDOR 152	3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING STOREFRONT DOUBLE DOORS TO REMAIN	21	IT TECH 125	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E14	COMMON CORRIDOR 152	(2)3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED WOOD DOUBLE DOORS TO REMAIN	22	OFFICE 126	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E15	COMMON CORRIDOR 152	3'-0"	-	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED WOOD DOOR TO REMAIN	23	OFFICE 127	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E16	CORRIDOR 153	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED WOOD DOOR IN NEW PAINTED RATED FRAME	24	WOMEN 128	3'-0"	8'-0"	1 3/4"	C	5	5	A15	A15	A15	-	5	5	5	-	NEW SOLID CORE WOOD DOOR/CLOSER/PUSH-PULL
E17	BREAK 155	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED DOOR & FRAME TO REMAIN AND BE REPAINTED	25	MEN 129	3'-0"	8'-0"	1 3/4"	C	5	5	A15	A15	A15	-	5	5	5	-	NEW SOLID CORE WOOD DOOR/CLOSER/PUSH-PULL
E18	UNISEX 156	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED DOOR & FRAME TO REMAIN AND BE REPAINTED	26	DIRECTOR PURCHASING 131	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
E19	JANITOR 157	3'-0"	7'-0"	-	-	-	-	-	-	-	-	-	-	-	-	EXISTING RATED DOOR & FRAME TO REMAIN AND BE REPAINTED	27	PURCHASING 132	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	28	DIRECTOR IT 133	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	29	DIRECTOR IT ADMIN 134	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	30	MARKETING 135	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	31	FUTURE 136	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	32	MARKETING 138	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	33	FUTURE 139	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	34	MARKETING 140	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	35	MARKETING 141	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	36	GENERAL COUNSEL 142	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	37	MARKETING 143	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	38	MARKETING 144	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	39	DIRECTOR MARKETING 145	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	40	CEO 146	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	41	DIRECTOR HR 148	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	42	HALLWAY 147	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	43	SMALL CONF. 149	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	44	DIR. CUSTOMER CARE 150	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR
																	45	TRAINING 151	3'-0"	8'-0"	1 3/4"	A	1	1	A15	A15	A15	-	1	1	1	-	NEW SOLID CORE WOOD DOOR

DOOR & HARDWARE NOTE

- LOOKS TO BE KEY OPERATED FROM THE OUTSIDE AND OPERATED FROM THE INSIDE BY A THUMB LATCH.
- ALL DOORS, EXCEPT AT CLOSETS,